

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1101  
NNE  
> 1  
1.443 mi.  
7620 ft.

COMMERCIAL  
2085 OCEAN PARKWAY  
BROOKLYN, NY 11223

NY Spills S125359328  
N/A

Relative:  
Higher

Actual:  
13 ft.

SPILLS:

Name: COMMERCIAL  
Address: 2085 OCEAN PARKWAY  
City,State,Zip: BROOKLYN, NY 11223  
Spill Number/Closed Date: 1905400 / 2019-08-30  
Facility ID: 1905400  
Facility Type: ER  
DER Facility ID: 543415  
Site ID: 593423  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2019-08-21  
Investigator: HSSEKHON  
Referred To: Not reported  
Reported to Dept: 2019-08-22  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2019-08-22  
Spill Record Last Update: 2019-08-30  
Spiller Name: Not reported  
Spiller Company: PROMONT CONSTRUCTION  
Spiller Address: Not reported  
Spiller Company: 999  
  
Contact Name: DANNY SINGH  
DEC Memo: "8/22/19 - Sekhon During delivery of construction materials (plywood) the delivery truck capsized onto the most southern section of the above-mentioned site along Avenue U. RSK Environmental Group contacted Riteway Industries Corp. (RIC) to respond to the spill cleanup. Riteway figured out that approximately 5-7 gallons of hydraulic fluid was discharged onto the blacktop of the street. RIC proceeded to apply oil absorbent granules and pads to contain the spill. A total of one (1) 55-gallon DOT approved drum was filled with remediated materials that was generated from the cleanup. RIC removed from drum from the site for proper disposal and the waste disposal manifest is pending. RSK performed a site inspection on August 22, 2019 and confirmed that the spill area was cleaned up and dusted with cement powder. 8/30 - Sekhon 7am - Site was inspected by DEC Sekhon, Spill cleaned up to satisfaction. Case closed."  
  
Remarks: "boome truck delivering equipment and capsized on sidewalk, leaking on property. clean up completed last night, still stain on sidewalk"

All Materials:

Site ID: 593423  
Operable Unit ID: 1341014

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit: 01  
Material ID: 2350861  
Material Code: 0010  
Material Name: hydraulic oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: Not reported  
Recovered: Not reported  
Oxygenate: Not reported